



NOTE:
 SUITABLE BACKFILL SHALL BE SELECTED FROM EXCAVATED MATERIALS AND IS SUBJECT TO THE APPROVAL OF THE NADPW. FRACTURED ROCK OR HAMMERED/BROKEN LEDGE SHALL NOT BE USED FOR BACKFILL.



TOWN OF NORTH ATTLEBOROUGH, MASSACHUSETTS
 DEPARTMENT OF PUBLIC WORKS

Date Last Updated:
 03/02/2023

WATER MAIN TRENCH DETAIL
 N.T.S.

Detail Number:
 W-4.1